



Predictive Maintenance Services, Inc.
 515 Morris Street
 Uhrichsville, Ohio 44683
 740-922-2025

ISO 9001:2000

Unit ID: BLUE LUBE
 Client ID: 4142
 Unit Type:
 Unit Make:
 Unit Model:
 Equip Type: PIPE GASKET LUBE
 Equip Serial:

ATTENTION CODE:
FYI

Lube Type:
 Grade:
 Capacity:

REMARKS

* FLASH POINT = 225F. CONE PENETRATION AT 77 DEGREES F = 342 MM.
 NOTE: FLASH POINT COULD ONLY BE ACHIEVED AFTER DRIVING OFF WATER
 * TEST RESULTS PROVIDED FOR INFORMATION ONLY.

ATTENTION CODES
 ---- Slightly Above Normal
 == Caution
 **** Severe
 !!!! Critical
 LLL Slightly Below Normal
 BBB Caution - Below
 CCC Severe - Below
 DDD Critical - Below

WEAR METALS										MULTISOURCE					ADDITIVES							
IRON	CHROMIUM	LEAD	COPPER	TIN	ALUMINUM	NICKEL	SILVER	TITANIUM	VANADIUM	SILICON	BORON	SODIUM	POTASSIUM	MAGNESIUM	CALCIUM	PHOSPHORUS	ZINC	MOLYBDENUM	BARIUM	VISC 40c	VISC 100c	VISC INDEX
Sample: 175720 Date Taken: 10/31/2008 Date Tested: 11/4/2008 Hrs/MIs [Oil: 0 Unit: 0]																						
0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

AN	BN	>4(c)	>6(c)	>14(c)	>25(c)	>50(c)	>100(c)	ISO	% WATER	K FISCH	FUEL	GLYC	SOOT	OXI	NIT
0	0	0	0	0	0	0	0	0/0/0	0	0			0	0	0

175720

LAB USE ONLY:

ATTN: STEPHEN CAREY
 WHITLAM PLUMB=PRO
 PO BOX 380
 200 WEST WALNUT ST
 WADSWORTH, OH44282

Remarks and comments are advisory only and are based on the assumption that the sample is representative and data submitted is valid. Missing information limits the evaluation. No Warranty is expressed or implied.